27 February 1962

COR 319 (HB-4)

25X1A Subject: Contract Spare Parts Gentlemen: Pursuant to the provisions of subject contract 25X1A delivered Spare Parts under the order except as follows: Lead Screw 1 each Nut-lead screw 3 each 2. 25X1A Nut-lead acrew 3 each Tube, Cathode Ray (Pll) 1 each Tube, Cathode Ray (P16) 2 each 5. 6. Wiper, Commutator 1 each

Delay in delivery is based on the following:

Items 1, 2 and 3 - These items were rejected and returned to Vendor for rework. Redelivery is expected during week of 26 February 1962 and to be shipped by 1 March 1962.

Items 4 and 5 - These items are still under evaluation by Vendor and cannot be ordered until evaluation is complete. They will be delivered in March when the preferred vendor is selected.

Item 6 - This item will be delivered as soon as additional parts are fabricated.

Declass Review by NIMA/DOD

SLUMLT

This document contries information affecting the national defense of the United Engine in the standard of the Hodorice Laws, Title 10, U.S. C. The transaction or the revelation of its and in any manner to an unauthorized person is prohibited by isw.

27 February 1962

-2-

COR 319 (HB-4)

In addition to the foregoing, certain nomenclature changes, additions and deletions are required as follows:

Changes - Long Down Time Spares

25X1A	Change from:	Focus Coil Syntronic				
25X1A	to: Reason:	Focus Coil Syntronic Manufacturer's substitution - model number changed				
25X1A	Change from: to:	Potentiometer (1K-1/4 W Miniature) Potentiometer (1K 0.2 W Miniature)				
25X1A	Reason:	Incorrect on original list				
25X1A	Change from: to:	Motor Motor				
25X1A	Reason:	nust be modified to new part number				
	Changes - Short Do	m Time Spares:				
25X1A	Change from: to: Reason:	Diode (100 PJ5A) Diode (100 V5A) Incorrect listing on original list				
25X1A	Change from:	2 required (per list) Transistor FNP				
25X1A	to: Reason:	4 required (per list) Transistor PNP Substitution for plus original quantity				
	Deletions - Short					
25X1A	Delete:	2 required (per list) Transistor PNP 25X1A				
25X1A	Reason:	Not available - substitute Difference in price				
25X1A	Delete:	founting Plate 1 place only - Item 33 on Page 1 of 3				
	Reason:	Duplication of numbers. Original listing is Item 26, on Page 1 of 3 To be deducted				
	Additions - Short	Down Time Spares 25X1A				
25X1A	Add: Reason:	2 required (per list) Dashpot Equipment added since original list.				

SECRET

Approved For Release 2001/07/16 : CIA-RDP78B04747A000600100009-6

COR 319 (HB-4)

	27 February 1962	-3-	COR 319 (HB=4)		
5X1A	Add: Reason;	6 required (per Overlooked on original list. Price \$.06 each , ,			
	The deletions and	additions affect the contract	price as follows:		
25X1A	Deleted Added				
25X1A					
	contract price, a	Il require a change to the cont nd Spares list changes. If des date in order that any and all hange order for the contract.	ired, this change may be		
25X1A	If additional information is required, please contact Manager, Contract Administration.				
	Very truly yours,	<u>, </u>			
25X1A					

Vice President, General Manager

REB: 8b

25X1A

¢	Ľ	Ç,	Ti	ľ	1